



## **Addendum For Turbo C, Turbo AC & Turbo SC**

**These Turbo's have been updated with a New Feature:  
High Voltage Standby Mode.**

This feature applies when a flash unit is disconnected from the flash cable while the other end of the cable is still connected to a Turbo *C*, *AC*, or *SC*, or when some flash units go to "sleep" (such as Canon 580EX II). In either case, the Turbo High Voltage Output goes to High Voltage Standby Mode, and the "flash" indicator "⚡" LED blinks once every 2 – 3 seconds. After a flash is reconnected to the cable, or the flash wakes up from "sleep", Turbo *C*, *AC*, and *SC* will return to normal operation, and Turbo's flash indicator "⚡" LED lights steadily.

If the Turbo's "flash" indicator LED still continues to blink while the flash cable is connected to the flash and Turbo, your Turbo cable has a problem and should be replaced.

QUANTUM INSTRUMENTS INC.  
10 Commerce Drive, Hauppauge, New York 11788  
Tel: 631-656-7400 • Fax: 631-656-7410  
[www.qtm.com](http://www.qtm.com)



P646C